



Visit our web site at www.bi-tec.com

P.O. Box 497 • #2 Industrial Park Dr. • Morrilton, Arkansas 72110 • Fax (501) 354-3019 • Phone 1-800-535-8597

General Technical Bulletins

INDEX

Bulletin No.	Date	Title/Subject	Page
1001	12/00	Why Determine Tensile Strength.....	3, 4
1002	6/00	Cold Weather Applications	5
1003		Replaced by 1012	
1004		Replaced by 1012	
1005	1/01	Plastic Cement Incompatibility	7
1006		Replaced by 1012	
1007		Replaced by 1012	
1008-2	3/04	Tectum Decks & UL/FM Requirements.	9
1009-1	3/04	Vented Base Sheets.....	11
1010-1	3/04	Wood Decks/Wind Uplift Resistance.....	13
1011	4/03	Installation of Modified Bitumen using Cold Adhesive Application	15
	1/01	BITEC Memo Regarding Tech Bulletin #1012-1.....	17
1012-1	7/91	Coatings and Adhesives Approval Update.....	19
1013	10/02	Moisture Vents - Recover Situations	21
1014	1/01	Pitch Pans	23, 24
1015-2	3/04	UL Classification Listings	25
	3/04	UL Listings and Requirements Chart	26
1016	5/03	Roof Insulation Fastening/Attachment	27
1017	2/03	Recover Boards and Approved Insulations	29, 30
1018	4/02	Extended Warranty Requirements	31
1019-1	12/02	Roof Maintenance Recommendations	33, 34
	3/04	Abbreviated Metric Practice Guide for the Roofing Industry	35, 36